

P O R S C H E
C A R S
N O R T H
A M E R I C A
I N C .


Technical Bulletin		Model 6 Cyl.	Group 4
Subject	Creaking / Grinding Noises in the Front Suspension	Part Identifier 4080	Number 9605

ATTENTION: Service Manager / Service Technician

This bulletin replaces Technical Bulletin Group 4, number 9605, dated 4-9-96.

Models Affected: *911 Carrera as of Model Year 1995 and 911 Turbo as of Model Year 1996*

Concern: Creaking or grinding noises from the area of the front suspension can be caused by rotation of the stabilizer in the stabilizer rubber mounts. These noises can be more pronounced in cold and wet weather.



General Information: As of the following VIN numbers, a different stabilizer rubber mount with a reduced preload on the stabilizer bar is installed in production:

WPOAA2 99 7 SS 32 3709 Coupe
WPOCA2 99 7 SS 34 2592 Cabriolet

Repair Information: If a customer complains of grinding or creaking noises in the front suspension of vehicles produced before the above mentioned VIN numbers, the stabilizer rubber mounts should be replaced. Use Vaseline on the mounting surface of the stabilizer bar prior to installation of the rubber mounts.

If a complaint of creaking or grinding noise from the front suspension is received regarding vehicles produced after the above mentioned VIN numbers, an inspection of the rubber mounts should be made. If the rubber mounts are severely deformed, replacement of the mounts is required. Be certain to lubricate the mounting surface of the stabilizer bar with Vaseline before the stabilizer mounts are installed.

Parts Information:

Stabilizer Mount (M 491)	964 343 792 20
Stabilizer Mount (Standard)	964 343 792 21
Stabilizer Mount (M 030 and Turbo)	964 343 792 22

Warranty Information:	Damage Code	Description	Labor Operation	T.U.
	4080 10 0002	Inspect/Replace Stabilizer Bar Mountings	4080 2000	40

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1996 Porsche Cars North America, Inc.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____
Distribution	Asst. Manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____
Routing						

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1996 Porsche Cars North America, Inc.
All rights reserved. Cannot be reproduced without written permission.
Service & Parts Publications.



SERVICE