

Technical Bulletin

Model
6 Cyl.

Group
3

Subject

Damaged Leather Shift Boot

Part Identifier
3405

Number
9502

ATTENTION: Service Manager / Service Technician

Model Affected: *911 Carrera 4 Model Year 1995*

Concern: When shifting into reverse gear, the leather shift boot may be pinched between the boot frame and the shift lever, damaging the shifter boot.


General Information: To prevent this from occurring, a modified shift lever has been used since January 10, 1995 production, as of the following VIN numbers:

99 6 SS 32 3006 - Coupe
99 9 SS 34 2562 - Cabriolet

If a 1995 911 Carrera 4 produced before the above mentioned VIN numbers has a damaged leather shift boot, a new shift lever, part number 993 424 015 01, should be installed along with a new leather shift boot.

Repair Information:

- 1) Remove the old shift lever boot and shift lever. Install the new shift lever and a new shift lever boot.
- 2) Place the shift lever into the neutral position. The shift lever will automatically move to the 3rd - 4th gear shift gate. When adjusted correctly, the shift lever will be at a 90°(vertical) angle to the tunnel.
- 3) Operate the shifter through all gears. There must be equal free play to the front and rear of the console when each gear is fully engaged. If the freeplay is not equal, adjust the ball socket (a) on the shifter guide tube (b). One full turn of the ball socket is equal to 3mm to 5mm of shifter movement.



IMPORTANT: The ball socket cups on both ends of the shifter guide tube must be aligned with each other to avoid binding of the shift lever and damage to the ball socket cups. Be certain to maintain this alignment when tightening the ball socket lock nut.

Parts Information:

Description	Part Number	Color Code
Shift lever	993 424 015 01	
Shift lever boot/knob	993 424 075 00	8YR Black 6XL Classic Grey H24 Midnight Blue T15 Chestnut Brown 3QN Marble Grey 4YU Cashmere Beige

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.



Technical Bulletin

Model
6 Cyl.

Group
3

Subject

Damaged Leather Shift Boot

Part Identifier

3405

Number

9502

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1995 Porsche Cars North America, Inc.

Dealership	Service manager _____	Shop foreman _____	Service technician _____	_____	_____	_____	_____
Distribution	Asst. manager _____	Warranty admin. _____	Service technician _____	_____	_____	_____	_____
Routing							

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Variocam® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1995 Porsche Cars
North America, Inc.
All rights reserved. Cannot be
reproduced without written permission.
Service & Parts Publications.



SERVICE

Page 2 of 2
February 28, 1995