

911 Turbo (993)

2/01 975

9

Binder - Service Technical Bulletins

W301-Replacement of Engine Wiring Harness

Vehicle Type:

911 Turbo (993)

Model Year:

MY 1996 (T)

Concern:

Engine wiring harness

Information:

Porsche is requesting that the engine wiring harness be checked and/or replaced on a certain range of model year 1996 911 Turbo (993) vehicles.

Based on field information and internal testing, Porsche AG has concluded that the insulation of the wires of the wiring harness may deteriorate. The deterioration of multiple wires may result in shorts which affect the proper function of the engine. Rough engine running, stalling, inability to start the engine due to a dead battery, starter malfunction, and illumination of the Malfunction Indicator Light ("Check Engine" warning lamp) are symptoms for this problem.

The engine wiring harness part number must be checked on all affected vehicles. Depending on what you find when you inspect the vehicle, the wiring harness may then also need to be replaced.

Affected Vehicles:

A total of 779 U.S. and 65 Canadian vehicles fall within the scope of this Service Action.

Very Important! Not every vehicle in the below listed range may be affected. Use the ranges below as a general guideline. Alternatively, the VIN can be checked in the Porsche E-DCS/WWS for confirmation of an open service action (or recall campaign). Also, the VIN can be checked via the VRU (Voice Response System) for any open listing.

The affected Vehicle Identification Numbers are contained in the following VIN-Ranges:

WP0AC2992TS375065 to WP0AC2992TS375924 (U.S. Vehicles) WP0AC2996TS375067 to WP0AC299XTS375895 (Canadian Vehicles)

Customer Notification

Porsche Cars North America, Inc. will notify all known Vehicle Owners directly by First Class Mail during the week of October 21, 2002, as per attached Notification Card located in Attachment "A"



911 Turbo (993) 9752 **2/01**

Technical Information

Work Procedure:

See Attachment "B".

Administrative Procedure:

See Attachment "C"

Customer Reimbursement Procedure:

See Attachment "D"

Parts Required:	Part Number 000 043 204 62	Quantity 1	Description Part set for Turbo engine Contains: 1x - Engine wiring harness (993 607 016 12) 1x - Adapter for heating connector (connected to wiring harness) 3x - Tie wrap
	964 110 227 00	1	Seal
	999 707 326 40	2	O-ring
	999 512 460 00	1	Single-lug clamp

PORSCHE

Technical Information

911 Turbo (993) 2/01 9752

Attachment "A"

Customer Notification Card

SERVICE ACTION NOTICE

Re: W301 Customer Service Campaign Action

Dear Porsche Owner:

Our records indicate that you are the Owner of a Porsche 911 Turbo (993), model year 1996 vehicle that may be affected by a Workshop Service Action concerning the engine wiring harness.

Porsche AG, initiated this voluntary customer service campaign action based on field information and internal testing, and concluded that the insulation of the wires of the harness may deteriorate. Deterioration of multiple wires may result in shorts which affect the proper function of the engine. Rough engine running, stalling, inability to start the engine due to dead battery, starter malfunction, and illumination of the Malfunction Indicator Light ("Check Engine" Warning Lamp) are symptoms for this problem.

In order to avoid such faults arising, the engine wiring harness of your Porsche must be checked. Depending on the results of these checks, the wiring harness may then also need to be replaced.

You should arrange for an appointment with your Porsche dealer as soon as possible to have the required work performed. The necessary parts to perform this service campaign action will be available at your Porsche dealer. The estimated time to perform the repair is approximately six to eight hours and will be completed at no charge to you. Please allow yourself and your Porsche dealer additional time to complete the repairs.

If you have already paid for the engine wiring harness of your Porsche to be replaced or repaired due to this particular problem, you will still need to have your vehicle inspected. Please send all documents in the enclosed postage-paid envelope for our review. The costs that you previously incurred may be reimbursable to you.

If your Porsche dealer is unable to perform this repair within a reasonable period of time, you may call or write:

Porsche Cars North America, Inc. 980 Hammond Drive, Suite 1000

Atlanta, Georgia 30328

Attention: Customer Commitment Telephone: 1-800-Porsche (767-7243)

We sincerely regret any inconvenience this Customer Campaign may cause, and kope you understand our interest in performing this work promptly so that you can be satisfied with your Porsche automobile. Please accept our apologies for this unplanned service visit. Sincerely, Porsche Cars North America, Inc.



BUSINESS REPLY CARD

FIRST CLASS

PERMIT NO. 26231

ATLANTA, GA

POSTAGE WILL BE PAID BY ADDRESSEE

Porsche Cars North America, Inc. Attn: Customer Commitment 980 Hammond Drive, Suite 1000 Atlanta, Georgia 30328-9735 NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

©2002 Porsche Cars North America, Inc.

Service

Date: 10-18-02 Page 3 of 30



911 Turbo (993) 9752 **2/01**

Technical Information

Attachment "A" (cont'd)

Customer Notification Card

	SE	RVI	CE	AC	TIC	N	NO	T	CE			
fehicle dentification Number									Rec W3			Dealer #
			•									
you no longer omplete this po	own this au	tomobile	e or yo	our ac	ddress	is dif	feren	t fron	n that	show	n be	elow, plea
трете тів ра	ostage pre-p	paid card	i, det	ach a	ınd ret	urn.	feren	t fron	n that	show	n be	elow, plea:
you no longer omplete this po My correct ac	ostage pre-p	paid card	i, det	ach a	ddress ind ret	urn.	feren	t fron	n that	show	n be	elow, plea
трете тів ра	ostage pre-p	paid card	d, det	ach a	end ret	urn.	feren	t fron	n that	show	m be	elow, plea
My correct ac	ddress is:	or 🖸	d, det	ach a	end ret	urn.	feren	t fron	n that	show	m be	
My correct ad	ddress is:	paid card	d, det	ach a	end ret	urn.	feren	t from	n that	show	m be	

Date: 10-18-02 Page 4 of 30

Service

911 Turbo (993) **(2/01** 9752

Attachment "B"

Work Procedure:

Follow the steps below and refer to the enclosed excerpt from the Technical Manual at the end of this bulletin for the actual work procedure.

- 1. Check the part number of the engine wiring harness. Use the criteria in section 97-2, page 1 to determine if the wiring harness needs to be replaced.
- 2. If the part number on the harness matches up with a part number listed in the table located in section 97-2 page 1, the harness needs to be replaced. Replace the harness then go to step 4.
- 2. If the part number on the harness does not match up with a part number listed in the table located in section 97-2 page 1, the harness does not have to be replaced. Continue with step 4.
- 4. Enter the campaign in the Warranty and Maintenance book.

Literature:

911 Carrera (993) Technical Manual, Group 9:

> Repairs: 97 52 55 - Replacing the wiring harness for the naturally-aspirated engine (enclosed with this bulletin)

©2002 Porsche Cars North America, Inc.

Service

Date: 10-18-02 Page 5 of 30

Attachment "C"

Administrative Procedure, Service Action W301

Engine Wiring Harness

Warranty claims should be submitted via e-dcs

Note: Always check for open recall status under the appropriate e-dcs menu options.

Affected VINs:

See attachment "A"

Labor Operation:

Will be automatically inserted along with the necessary parts when the damage code is entered.

Warranty Code:

R

Scope 1:

Checking the part number of the engine wiring harness.

Damage Code:

W301 066 000 1 (for W301)

Repair Code:

1

Time Units:

80 TU

Scope 2:

Checking and replacing the engine wiring harness on MY 1996 (T).

Damage Code:

W301 066 000 1 (for W301)

Repair Code:

2

Time Units:

640 TU

Parts:

Part Number Qty. Description 000 043 204 62 Wiring Harness Kit 964 110 227 00 1 Seal 2

999 707 326 40

0-ring

999 512 460 00

1 Single-lug clamp

In cases where the recall cannot be performed, submit this information on a claim via e-dcs with the appropriate disposition code by inserting the code in the last digit of the damage code, as shown below.

Disposition/Repair code

- 3 Total Loss
- 4 Vehicle Stolen
- 5 Vehicle left North America
- 6 Customer Moved/address unknown
- 7 Vehicle sold, new owner information
- 9 Customer refused to comply

Date: 10-18-02 Page 6 of 30

Service



911 Turbo (993) **2/01** 9752 9

Owner name and address change

If the owner name and address are shown incorrectly, submit a correction using the name/address postcard from the Warranty Maintenance Booklet (or Recall mailing), or report the change to the Warranty Department via e-dcs, including VIN.

Attachment D:

Reimbursement to customer for previously repaired vehicles.

Important! The harness check must be performed before we will reimburse the customer.

The customer was sent a form and a postage paid envelope with the Service Action notification. The customer must completely fill out the form, attach the appropriate receipts, and mail it to PCNA to be considered for reimbursement. PCNA will not be responsible to reimburse for incidental expenses related to the wire harness replacement.

The customer must follow these steps to be considered for reimbursement:

- Repair order in which the harness replacement is listed, and why it was replaced. We will only reimburse customers if the harness was defective as listed in this bulletin.
- 2. Receipt of payment showing the amount that was paid for the replacement.
- 3. Complete the reimbursement form. If the customer has misplaced the reimbursement form, copy the form on the back of this page and provide it to him/her.
- Send in the documents to Porsche Cars North America, attention W301 Customer Reimbursement. We will review the documents and determine if a check will be issued.
- 5. Porsche Cars North America will not reimburse for incidental expenses related to the repair or replacement of the wiring harness as described in this Service Action.

Porsche Cars North America, Inc. Attn: W301 Customer Reimbursement 980 Hammond Drive, Suite 1000 Atlanta, Ga. 30328

Important Notice: Porsche Cars N.A. Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do you have the properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

©2002 Porsche Cars North Ar	merica, Inc.		Se	rvice				D	ate: 10-18-02
Porsche, the Porsche marque, 911 Porsche automobiles are trademari	, Carrera, Boxster, Cayenn is of Dr. Ing. h.c.F. Porsche	e, Tiptronic, Va AG.		a, Tequipment,	Service Technician PCCB, PCNA EDCS, and PC	M are register	ed trademarks	. The distinctive	shapes of the
Dealership Distribution Routing	Service Manager Asst. Manager		Shop Foreman Warranty Admin.		Service Technician			- roscie cars	North America, Inc

Page 7 of 30

911 Turbo (993) 9752 2/01

Technical Information

PORSCHE

Customer Reimbursement Application Form - Service Action W301

To Ensure Prompt turn around, please complete all required fields and include a copy of the paid invoice.

Although repairs to the wiring harness were previously completed, it is extremely important to have the wiring harness inspected and, if necessary, replaced at your local Porsche Dealership. If you have not completed this Service Action, Porsche Cars North America cannot issue a reimbursement for past repairs. Please complete the section below and provide a copy of your current invoice. We will only issue a reimbursement if the wiring harness was defective as described in this Service Action. Porsche Cars North America will not reimburse for incidental expenses related to the repair or replacement of the wiring harness as described in this Service Action. Thank you.

Date of Repair:	Mileage/Kilometers:
Dealer Name:	Repair Order Number:
Owner Information: Vehicle id	dentification Number (VIN):
Current Owner? Yes 🗆 No 🖬 If "No", w	was vehicle sold to a Dealer or private person? Yes 🗅 No 🗅
f known, please provide address of new	owner:
New Owner Name:	
Address:	
City:	State/Prov.: Zip/Postal Code:
Your Name:	
Address:	
City:	State/Prov.: Zip/Postal Code:
Previous Repair Information: (Impor	
Previous Repair Information: (Impor Date of Repair:	rtant: Please attach copy of paid invoice.) Mileage/Kilometers: Repair Order Number:
Previous Repair Information: (Importance of Repair: Dealer Name: Independent Repair Facility: Yes No No	rtant; Please attach copy of paid invoice.) Mileage/Kilometers: Repair Order Number: (Please Check One)
Previous Repair Information: (Importance of Repair:	rtant: Please attach copy of paid invoice.) Mileage/Kilometers: Repair Order Number:
Previous Repair Information: (Importante of Repair:	rtant: Please attach copy of paid invoice.) Mileage/Kilometers: Repair Order Number:
Previous Repair Information: (Importante of Repair:	Mileage/Kilometers: Repair Order Number: (Please Check One) K One) Total reimbursement requested: \$ d to replace the wiring hamess (or applicable repairs) will be considered for reimbursement to six weeks to process your request. Incomplete forms will be returned
Previous Repair Information: (Importante of Repair:	Mileage/Kilometers: Repair Order Number: (Please Check One) K One) Total reimbursement requested: \$ d to replace the wiring hamess (or applicable repairs) will be considered for reimbursement to six weeks to process your request. Incomplete forms will be returned
Previous Repair Information: (Important of Repair:	Mileage/Kilometers:

Page 8 of 30

Table of Contents

9 Electrical system 97 Wiring 97 52 55 Replacing the wiring harness for the turbocharged engine 97-2 page 1 Check the wiring harness for the engine 97-2 page 1 Wiring harness connections 97-2 page 2 Remove the wiring harness for the engine 97-2 page 4 Installing the wiring harness for the engine 97-2 page 1

Table of ContentsPrinted in Germany, 2002

master

@2002 Porsche Cars North America, Inc.

Service

Date: 10-18-02 Page 9 of 30


Replacing the wiring harness for the turbocharged engine

Check the wiring harness for the engine


- Protect the protruding upper part of the lock on the engine compartment lid, for example with a piece of hose (danger of injury). Put rear assembly-protection cover on the vehicle.
- 2. Remove air guide bracket from the charge air cooler.

Note!


- The rear fastening nuts of the lower charge air cooler mounting can fall to the floor after they have been unscrewed.
- The pressure pipes between the charge air cooler and turbocharger must be sealed (foreign objects).
- 3. Remove charge air cooler.
- Remove the cover from the relay carrier in the engine compartment. Unscrew the three screws -arrows- for this purpose.



5. Check the part number of the wiring harness. The part number is affixed to the wiring harness -arrow- in the relay carrier in the engine compartment. If one of the following part numbers has been printed on the wiring harness or if the part numbers can no longer be read, the wiring harness for the engine must be replaced.



	Part number	
1	993.607.016.11	




97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002 993-Turbo

97-2 page 1

Date: 10-18-02 Page 10 of 30

Service

Wiring harness connections



97-2 page 2

97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002

©2002 Porsche Cars North America, Inc.

Service

Date: 10-18-02 Page 11 of 30

No.	Designation	Qty.	Removal	Installation
1	Reversing light switch con- nections	2		
2	Starter connections	2	Disconnect battery	
3	Injection valve connections 4 - 6	3		Cyl. 6 = blue; Cyl. 5 = brown; Cyl. 4 = white
4	Frequency valve connection	1		
5	Oil pressure sensor con- nections	1		
6	Generator connections	3	Disconnect battery	Make sure the cable sleeves are installed correctly.
7	Oil temperature sensor connection	1		
8	Secondary air pump con- nections	2		
9	Tank vent connection	1		
10	Boost pressure sensor connection			
11	Ground cable	1		
12	Fan belt monitoring con- nection	1		
13	Connections for ignition coil	2		
14	Hall sender connection	1		
15	Connection, heating switch-over valve	1		
16	Connection, heating bal- last resistor			
17	Connection NTC heater blower	1		
18	Injection valve connections 1 - 3	3		Cyl. 3 = blue; Cyl. 2 = brown; Cyl. 1 = white
19	Fresh-air blower connec- tion	1		
20	Wiring harness connecting plug	3	Disconnect battery	

97 52 55	Replacing	the wiring	harness	for the	turbocharged	engine
Printed in G	ermany, 2002	1			993 Turbo	

97-2 page 3

Date: 10-18-02 Page 12 of 30 Service



Caution!

Danger of material damage if the vehicle is raised incorrectiv!

Raise the vehicle at the prescribed jacking points!



/ Caution!

Risk of damage!


 The battery must be disconnected when working on electrical components.

Remove the wiring harness for the engine



Note!

- Since the Motronik has several adaptive systems, terminal 26 of the DME connector is permanently positive.
- . If the connector is disconnected from the control module or if the vehicle battery is disconnected, the engine must first run 250 seconds before the first adaptation phase begins.
- The DME control module also has a non-volatile fault memory. Therefore, before disconnecting the battery, the fault memory must be read out and the radio code must be found out!
- 1. Disconnect the battery and cover terminal or battery.
- 2. Remove the heater blower or bypass air flap, disconnect the ballast resistor on the heating pipe, and clip it in again.
- 3. Remove the cover from the relay carrier in the engine compartment. Disconnect the plug connections carefully (risk of breakage). Counter when pulling off.



97-2 page 4

97 52 55 Replacing the wiring harness for the turbocharged engine 993-Turbo Printed in Germany, 2002

©2002 Porsche Cars North America, Inc.

Service


Date: 10-18-02 Page 13 of 30


- 4. Remove the air cleaner assembly and hot film air flow sensor. Disconnect the air flow sensor from the air cleaner housing. Take the air cleaner housing out of the rubber mounts. Unplug the air flow sensor and disconnect from the air cleaner housing by turning.
- 1 Idle speed control connection
- 2 Air flow sensor connection
- 3 Air-conditioning lines holder
- 4 Oil pressure sensor connections
- 5 Boost air temperature sensor connector
- 5. Remove the positive crankcase ventilation hose -arrow -.




The square fastening nuts of the air conditioning compressor holder screws can fall to the floor after they have been unscrewed.

- 6. Unscrew the four air conditioning compressor holder screws and release the clamp. Disconnect the plug connections and set the air conditioning compressor with a stable base down on the right side section.
- 7. Release the upper hose clamps (6 pieces / 3 left and 3 right) of the intake pipes.







97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002


993-Turbo

97-2 page 5


Date: 10-18-02 Page 14 of 30

Service


- 8. Disconnect the connector from the holder and release the hose from the tank vent -arrow- and remove.
- 1 Temperature sensor connection
- 2 Reference mark sender connection
- 3 Tank vent connection
- 4 Cruise control connection



Disengage the accelerator cables -arrows- and unscrew the screw of the counter holder. Press the accelerator cables out of the holder. Pull off the hose -1-.



10. Remove the center and right vent hose on the throttle body.




97-2 page 6

97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002


©2002 Porsche Cars North America, Inc.

Service


Date: 10-18-02 Page 15 of 30 Vent hose



11. Unscrew the screws -1- of the oil pressure sensor, disconnect the connector and disconnect the ground strap -arrow-. Lay the oil pressure sensor aside.



12. Pull all vacuum connections and connectors on the intake distributor. Remove the vent hose -1-. Mark the vacuum connections.



97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002

993-Turbo

97-2 page 7


Date: 10-18-02 Page 16 of 30

Service


1 check valve




All intake pipes must be sealed (foreign objects).



13. Remove the complete intake distributor (right, left, and center)



14. Remove the two rubberized clamps of the wiring harness.



97-2 page 8


97 52 55 Replacing the wiring harness for the turbocharged engine 993-Turbo Printed in Germany, 2002

©2002 Porsche Cars North America, Inc.


Service

Date: 10-18-02 Page 17 of 30


Rubberized clamp



15. Release the ground cable from the intake pipe.



- 16. Disconnect the connector from the fan belt monitoring and remove the fan belt monitor.
- 17. Remove the air cowl of the cooling fan. Unscrew the 3 screws and remove the air cowl.



97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002


993-Turbo

97-2 page 9


Date: 10-18-02 Page 18 of 30

Service


18. Release the cooling fan restraining strap and unscrew the screw. Tilt the cooling fan forward.



 Unscrew the generator housing screws. Release the cable from the generator. Press the rubber grommet out of the air cowl and pull out the lines.




20. Release the ignition wire retainer and unclip the fastening clip.




97-2 page 10


97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002

- 21. Unscrew the two screws of the fuel gallery on the right and pull out the tab washers of the injection valve. Then push the fuel gallery lightly toward the rear.
- 22. Unplug the connectors from the injection valves, distributor ignition, ignition coil (connections are screwed in), oil pressure sensor (connections are screwed in), oil temperature sensor and secondary air pump.
- 23. Pull the wiring harness approx. 100 mm under the crankcase vent tube toward the passenger compartment.
- 24. Remove thermal motor protection.
- 25. Remove the warm air pipe on the right -arrows-. To do this, unscrew the two hexagon socket head bolts and release the hose straps.





26. Remove the transmission vent hose and suction hose to the tur-bocharger. To do so, release the upper screw-type hose clamp-arrow- and the lower clamp -arrow-.



97 52 55 Replacing the wiring harness for the turbocharged engine

Printed in Germany, 2002


993-Turbo

97-2 page 11


Date: 10-18-02 Page 20 of 30

Service

27. Unscrew the ground cable **-arrow-** on the starter. To do this, unscrew the hexagon socket nut.




28. Release the connections from the starter -1 + 2- and cut off the 2 tie-wraps -arrow-.



29. Pull out reversing switch connector. To do this, pull out the rubber grommet and the two pins.

■



97-2 page 12


97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002

- 30. Pull out rubber grommet -arrow- from the wiring harness.
- 1 Wiring harness for the starter and reversing light switch
- 2 Wiring harness for the fuel distributor pipe




Note!

Carefully press the wiring harness past the pipes. Avoid damage.



31. Pull wiring harness up and out. Doing this requires a second person. One person must press the wiring harness from below through the opening in the engine compartment while the other person pulls the wiring harness out.




Installing the wiring harness for the engine

1. Feed the wiring harness through the opening in the engine compartment to the starter and reversing light switch.



The terminal 30 cable must be bound with the protective tube with two tie-wraps to the starter. Attach the protective caps to the cable clamp.

2. Screw in the connections on the starter -1 + 2- and tighten. Fasten the two tie-wraps -arrows- .



97 52 55 Replacing the wiring harness for the turbocharged engine

Printed in Germany, 2002


993-Turbo

97-2 page 13

Date: 10-18-02 Page 22 of 30


Service

3. Insert the reversing light switch connector. To do this, press in the two pins and mount the rubber grommet.




4. Fasten the ground cable **-arrow-** on the starter. Tighten the hexagon socket nut.

Tightening torque hexagon socket nut 46 Nm (34 ftb.).



 Install the transmission vent hose and suction hose to the turbocharger. To do so, fasten the upper screw-type hose clamp -arrow- and the lower clamp -arrow-.




97-2 page 14

97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002


6. Install warm air pipe on right -arrow-.

Tightening torque (M6 x 20, M6 x 12) 10 Nm (7.5 ftlb.)


7. Install thermal motor protection.



- 8. Guide wiring harness under the crankcase vent tube.
- 1 Line to starter and reversing light switch
- 2 Line to the fuel distributor pipe



 Lightly lubricate the rubber grommet -arrow- of the wiring harness and press it in. Ensure correct seating.



97 52 55 Replacing the wiring harness for the turbocharged engine

Printed in Germany, 2002

993-Turbo

97-2 page 15

Date: 10-18-02 Page 24 of 30

Service

Note!


Check the sealing rings of the injection valves, replace as necesssary and lubricate (e.g., WD 40).

 Position the screws -arrows- of the right fuel gallery and tighten. Install the tab washers of the injection valves. Ensure that the tab washers are seated correctly.

Tightening torque 10 Nm (7.5 ftlb.).

11. Connectors of the injection valves cyl. 4 - 6 are connected and the wiring harness is fastened to the fuel gallery.

Connector color	Cylinder
blue	6 -
brown	5
white	4




12. Guide the generator connection cable through the air cowl and press in the rubber grommet. Place the cable on the generator, lubricate slightly, and fasten. Press rubber grommet in the air cowl. Position generator cover and tighten.

Tightening torques

D+ cable (blue) 2 Nm (1.5 ftb.), D- cable (brown) 2 Nm (1.5 ftb.), and the B+ cable (red) 8 Nm (6 ftb.)

Fastening screws generator housing 10 Nm (7.5 ftb.).




Install the cooling fan and tighten the restraining strap with a hexagon socket head bolt.

Tightening torque 8 Nm (6 ft/b.)

14. Install the air cowl of the cooling fan. Tighten the screws.

Tightening torque 10 Nm (7.5 ftb.)



97-2 page 16


97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002

©2002 Porsche Cars North America, Inc.


Service

Date: 10-18-02 Page 25 of 30 15. Install fan belt monitor and unplug connector.


Tightening torque 10 Nm (7.5 ftlb.).



16. Slide the wiring harness holder on the holder of the ignition coil cable and fasten.



17. Fasten the wiring harness using the two rubberized clamps.



97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002 993-Turbo

97-2 page 17


Date: 10-18-02 Page 26 of 30

Service


Rubberized clamp

Tightening torque for hexagon-head bolts 10 Nm (7.5 ftlb.)

18. Position and tighten ground cable on the intake pipes.




Tightening torque 10 Nm (7.5 ftb.).



- 19. Insert the plug connections from the relay carrier into the engine compartment and mount the cover.
- 20. Connect the connectors of the injection valves 1 3, distributor ignition, ignition coil (connections are screwed in), oil pressure sensor (connections are screwed in), oil temperature sensor and secondary air pump.

Connector color	Cylinder
blue	3 .
brown	2
white	1




97-2 page 18

97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002


©2002 Porsche Cars North America, Inc.

Service


Date: 10-18-02 Page 27 of 30 21. Install the complete intake distributor (right, left, and center). Lightly oil the rubber of the intake pipes. Tighten the hose straps of the intake pipes.



22. Connect all vacuum connections and connectors on the intake distributor.



23. Connect the center and right vent hose on the throttle body.




97 52 55 Replacing the wiring harness for the turbocharged engine Printed in Germany, 2002 993-Turbo

97-2 page 19


Date: 10-18-02 Page 28 of 30

Service

Vent hose




24. Place the oil pressure sensor holder and tighten the screws - 1-. Fasten the ground strap -arrow-.



25. Engage accelerator cables -arrows-. Lightly oil the rubber of the accelerator cables. Tighten the accelerator cable holder. Connect the hose -1-. Ensure that the accelerator cables are seated correctly and tightly.

Tightening torque 10 Nm (7.5 ftlb.).



97-2 page 20

97 52 55 Replacing the wiring harness for the turbocharged engine
993-Turbo Printed in Germany, 2002

©2002 Porsche Cars North America, inc.

Service


Date: 10-18-02 Page 29 of 30

- 26. Fasten the connector on the holder (observe color code). Position and tighten the hose from the tank vent -arrow-.
- 1 Temperature sensor connection
- 2 Reference mark sender connection
- 3 Tank vent connection
- 4 Cruise control connection
- Install air-conditioning compressor. Connect connector. Position screws and tighten. Fasten air-conditioning lines in the holder.

31133

Tightening torque 28 Nm (21 ftlb.)

- 28. Mount the positive crankcase ventilation hose -arrow -.
- 29. Install the air cleaner assembly and hot film air flow sensor.
- 30. Mount the heater blower or the bypass air flap.
- 31. Install charge air cooler.
- 32. Mount the air guide bracket from the charge air cooler.
- 33. Connect the battery.



Note!

After the connector has been disconnected from the control module or if the vehicle battery has been disconnected, the engine must first run 250 seconds before the first adaptation phase begins.

34. Perform a function test.

97 52 55 Replacing the wiring harness for the turbocharged engine
Printed in Germany, 2002 993-Turbo

97-2 page 21

Date: 10-18-02 Page 30 of 30

Service