

Technical Bulletin

Model
911, 928S
944, 944 Turbo

Group
2

Subject:
Cleaning of Fuel Injectors

Part Identifier
2440

Number
8510

Partially restricted fuel injectors can be cleaned through the following procedure and material:

1. Fill up fuel tank.
2. Pour 20 ounces of "Techron" into the fuel tank.

Note: Techron is marketed by Chevron
3. The car should be driven until the fuel tank is half empty.
4. Refill the fuel tank.
5. This procedure, as outlined from point 1 to 4 should then be repeated 2 additional times.
6. To keep injectors clean, we recommend adding 20 ounces of Techron after 5 fuel tank refills. However, never more than 20 ounces per 3,000 miles.

PORETTI CASES NORTH AMERICA INC.



SERVICE

Page 1 of 1
Dec. 6, 1985