

Hydraulic Valve Lifters

Vehicle Type: **911 Carrera and 911 Turbo**

Model Year: **As of 1995 (S)**

Concern: **Hydraulic valve lifters**

Information: In the Parts microfiche dated **2/96**, frame **1/03/10**, position **25**, the application for the hydraulic lifters is incorrect. The following information should be applied if the hydraulic lifters need replacement.

**911 Carrera (993)
Engine Types: M64.07/08/23/24**

Part Number	Lifter Size
993 105 141 05	Standard
993 105 141 51	Size 1
993 105 141 61	Size 2

**911 Turbo (993)
Engine Types: M64.60**

Part Number	Lifter Size
993 105 141 03	Standard
993 105 141 50	Size 1
993 105 141 60	Size 2

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

©1997 Porsche Cars North America, Inc.

Dealership	Service Manager	Shop Foreman	Service Technician	_____	_____	_____	_____
Distribution	Asst. Manager	Warranty Admin.	Service Technician	_____	_____	_____	_____
Routing				_____	_____	_____	_____

The trademarks Porsche®, Targa®, Carrera®, Boxster®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.