

Technical Bulletin

Model
6 Cyl.

Group
4

Subject

New Type Oil for Steering Gear

Part Identifier
4800

Number
9606

ATTENTION: Service Manager / Service Technician

Model Affected: *911 Carrera 2 and 4, Model Years 1989 to 1994 , 911 Turbo, Model Years 1991, 1992 and 1994, and 911 Carrera (993) 1995 Model Year on*

Concern: In production, the power assist steering system is now filled with Pentosin CHF 11S fluid (green in color).

General Information: From the following VIN numbers, the power assist steering system is factory filled with Pentosin CHF 11S fluid:

As of March 25, 1996 from VIN:

99 9 TS 32 3082	Coupe
99 3 TS 34 1781	Cabriolet
99 8 TS 38 5439	Targa

Pentosin has been selected for use because of better and more uniform viscosity behavior at low ambient temperatures.

Vehicles of the model types affected produced before the above mentioned VIN numbers used ATF in the power assisted steering system. It is now permitted to use Pentosin CHF 11S in these vehicles as well.

ATF fluid and Pentosin CHF 11S fluid can be mixed. In vehicles produced before the above mentioned VIN numbers, Pentosin CHF 11S fluid can be used to top off the fluid reservoir.

The 1996 911 Turbo uses Pentosin CHF 11S fluid in the steering and hydraulic assisted clutch systems. In this system, ATF must not be mixed with Pentosin CHF 11S.

Vehicles having repairs made to the steering gear that involve loss of the steering fluid should be refilled with Pentosin CHF 11S fluid.

Parts Information: Pentosin CHF 11S fluid (1 Liter), part number - 000 043 203 33

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1996 Porsche Cars North America, Inc.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____
Distribution	Asst. Manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____
Routing						

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1996 Porsche Cars North America, Inc. All rights reserved. Cannot be reproduced without written permission. Service & Parts Publications.



SERVICE

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.