

Technical Bulletin

Model
6 Cyl.

Group
2

Subject:
Vacuum Lines

Part Identifier
24xx

Number
9605


ATTENTION: Service Manager / Service Technician

Models Affected: ***911 Carrera Model Years 1995 and 1996
911 Turbo Model Year 1996***

Concern: Care must be taken when working on or around any vacuum lines or fittings. Vacuum lines that become disconnected or kinked can cause faults in the OBDII system and/or problems in the heater A/C system.

General Cautions: When working on vacuum lines or vacuum fittings the following precautions should be observed:

1. When inserting a vacuum line into a fitting, insert the line to a depth of 8 - 10 mm. **Inserting a vacuum line too deeply into a fitting or manifold may cause the line to be blocked.** Use a felt tip marker or adhesive tape to mark the depth on the vacuum line.



2. Only use water as a lubricant when inserting vacuum lines into fittings.

Literature: 911 Workshop Manual (993), Volume 1, pages 24-17 to 24-21a.

P
O
R
S
C
H
E

C
A
R
S

N
O
R
T
H

A
M
E
R
I
C
A

I
N
C
.

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1996 Porsche Cars North America, Inc.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____	_____
Distribution	Asst. Manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____	_____
Routing							

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1996 Porsche Cars
North America, Inc.
All rights reserved. Cannot be
reproduced without written permission.
Service & Parts Publications.



SERVICE

Page 1 of 1
August 27, 1996