

Technical Bulletin

Model
6 Cyl.

Group
6

Subject

Cabriolet Top Motor

Part Identifier
6107

Number
9608

ATTENTION: Service Manager / Service Technician


Models Affected: **911 Carrera Cabriolet as of Model Year 1996**

Concern: Correct application of drive motor for the cabriolet top.

General Information: The cabriolet top is now driven by a single drive motor (formerly two motors). This change occurred in production as of December 5, 1995 from VIN 99 6TS 341001.

Repair Information:

When repairs are necessary to the cabrio top drive motor, mounting bracket or drive cables, it is important to identify the type of cabrio top drive that you are repairing. **Parts for both types of drives are available,** however, it is possible to install the new single motor drive parts into a vehicle previously equipped with two drive motors. This repair requires the use of the new drive motor parts (drive motor, drive cable left, drive cable right, mounting bracket left and mounting bracket right). It is not possible to combine old and new drive motor parts.



Parts information:

SINGLE DRIVE MOTOR - NEW VERSION

993 624 117 00	Electric drive motor
993 561 921 01	Drive cable, left
993 561 922 01	Drive cable, right
993 624 185 00	Mounting bracket left
993 624 186 00	Mounting bracket right

TWO DRIVE MOTOR - FORMER VERSION

911 624 117 00	Electric drive motor (X2)
911 561 107 65	Drive cable left
911 561 108 65	Drive cable right
964 624 185 65	Mounting bracket

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers. ©1996 Porsche Cars North America, Inc.

Dealership	Service Manager _____	Shop Foreman _____	Service Technician _____	_____	_____	_____	_____
Distribution	Asst. Manager _____	Warranty Admin. _____	Service Technician _____	_____	_____	_____	_____
Routing							

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Varioram® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1996 Porsche Cars North America, Inc. All rights reserved. Cannot be reproduced without written permission. Service & Parts Publications.



SERVICE

Page 1 of 1
September 3, 1996

PORSCHE CARS NORTH AMERICA INC.