

Technical Information

911 (996) 3/05

6006

Targa Glass Sliding Cover Lift Mechanism Causes Rattling Noises

Binder - 6, Body Equipment

Vehicle Type: 911 Targa (996)

Model Year: As of 2002

Concern: Lift mechanism of glass sliding cover causes rattling noises.

Information: Rattling noises in the area of the glass sliding cover may be heard on 911 Targa (996) vehicles. This is

caused by insufficient preload on the holder units of the lift mechanism. As of October 19, 2004, the holder units and connections of the lift mechanism of the glass sliding cover have therefore been mod-

Vehicles manufactured before October 19, 2004, for with a customer complaint "Lift mechanism of glass sliding roof causes rattling noises", must undergo modification.

This includes:

replacing the retaining frame and

- replacing the lift mechanism of the glass sliding cover.

The repair kits, part number, 996.562.933.01 (Retaining frame repair kit) and 996.562.906.00 (Lift mechanism repair kit) must be used for this. It is not permitted to replace individual components (mixed configuration of old/new).

The individual replacement parts of the Targa roof are available in the relevant version for repairs that must be carried out for other reasons as well as for vehicles manufactured up to October 19, 2004 which were modified.

Introduction: October 19, 2004, as of the following VIN:

99 95S 63 5085 USA



6 6006 911 (996) 6 6006 3/05

Technical Information

Action Required:

Vehicles with a customer complaint "Lift mechanism of glass sliding roof causes rattling noises", must be modified in accordance with the Workshop Manual.

For further information, see POSES, Workshop Manual, 911 Targa (996), Group 6:

> 60 06 19 - Removing and installing roof assembly - Targa,

> 60 28 19 - Removing and installing cover frame for sunroof - Targa,

> 60 35 55 - Replacing holder unit (drive mechanism) - Targa.

If this modification is made, the specified repair kits must be used on vehicles manufactured before the introduction date of October 19. 2004.

Up to VIN: 99 95S 63 5084 **– Use repair kits** (see parts information).

From VIN: 99 95S 63 5085 – Use individual replacment parts in accordance with PET catalog listing.

Parts Information:

Up to VIN: 99 95S 63 5084

Part Number Description

996.562.933.01 Retaining frame repair kit 996.562.906.00 Lift mechanism repair kit

Reference:

POSES, Workshop Manual, 911 Targa (996):

> Group 6: 60 06 19 Removing and installing roof assembly - Targa

60 28 19 Removing and installing cover frame for sunroof - Targa

60 35 55 Replacing holder unit (drive mechanism) - Targa

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Doi-tyourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

Dealership
Distribution
Routing

Dealership
Service Manager
Shop Foreman
Service Technician
Service Technician
Service Technician
Service Technician

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Tiptronic®, VarioCam®, PCM®, 911®, 45®, and the model numbers and distinctive shapes of Porsche's automobiles such as, the federally registered 911 automobile. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc., believes the specifications to be correct at the time of printing. However, specifications, standard equipment and options or Printed in the USA

Date: 3-31-05 Page 2 of 2